

Corrigendum

In tender document Tender Enquiry No.24/Patho/134(I)/2016-RISH (ADMN)

Dated: 05-08-2016

As per schedule, Pre- Bid meeting of "Tender for Quantitative Buffy Coat (QBC) System for the Department of Pathology" was held on 04-07-2016 at 03.00 PM, in the tender opening room.

After consideration by Store Purchase Committee following modification (deletions/additions/replacements) additions for Tender Enquiry No. 24/Patho/134(I)/2016-RISH (ADMN) has been made.

Following specification is being added after point srl no. 14 at page no 17 :

15. Principal company should also provide 1000 malaria tubes with coating of Acridine Orange stain with 13.0 µg or more and Potassium oxalate 0.3 mg or more alongwith sufficient consumables for 1000 malaria tests and 500 AFB slides.
16. The necessary required consumables should be quoted separately and the rate of the same should be frozen for next 5 years. Consumables rates will also be considered during price comparison. All spare parts and consumables should be available with the supplier or principals for a period of 10 years.
17. Consumables for 100 malaria tests and 100 AFB slides should be given free of cost.
18. Malaria atlas with images of Plasmodium falciparum and vivax, gametocytes and other stages of Plasmodium should be provided.
19. FM Scan device with minimum resolution of 5.0 MPX or more along with software to capture the positive images.
20. Data collection and processing unit: Branded computer with 2 GHz multicore processor, 6 GB RAM, DVD Writer, Original Windows 7 Professional or higher, 1 TB HDD, 23" TFT Monitor, Keyboard & Mouse. UPS should be provided with one hour battery backup.
21. Installation, training and commissioning should be done free of cost.

22. The after sales service should be available within 24 hours and with trained service personnel.
23. List of installations and feedback letters from the reputed government medical Institutes for this instrument supplied to assess performance and services.
24. 5 Years warranty and 5 years CAMC should be provided with supply of spare parts for atleast one year.